
Emergency Preparedness Roundtable 2018





Duarte Community Center – April 4, 2018





Mudslides 2016-17





Wide-Scale Disaster Effects







Potential Impacts




Lack of Potable Water






Great Southern California Shake-Out

US Geological Survey & the Southern California Earthquake Center





Water Loss – 1994 Northridge Quake




Case Study: Los Angeles Water Services Restoration Following the 1994 Northridge Earthquake

C.A. Davis, Los Angeles Department of Water and Power, Los Angeles, CA, USA

T.D. O'Rourke Cornell University, Ithaca, NY, USA

M.L. Adams and M.A. Rho Los Angeles Department of Water and Power, Los Angeles, CA, USA

Duante







GREY: Existing equipment

BLUE: New equipment being installed



Thank you for Attending! Any Questions?

